DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 69.28

WELDING INSPECTION REPORT

Resident Engineer: Pursell, Gary **Report No:** WIR-004132

Address: 333 Burma Road **Date Inspected:** 12-Oct-2008

City: Oakland, CA 94607

OSM Arrival Time: 630 **Project Name:** SAS Superstructure **OSM Departure Time:** 1530 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

CWI Name: CWI Present: Yes N/A No **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A Yes N/A **Electrode to specification:** No Weld Procedures Followed: Yes No N/A N/A **Qualified Welders:** Yes No **Verified Joint Fit-up:** Yes No N/A N/A N/A **Approved Drawings:** Yes No **Approved WPS:** Yes No Yes No N/A **Delayed / Cancelled:**

Bridge No: 34-0006 **Component: OBG Side Plates**

Summary of Items Observed:

Bay 4:

1) This QA performed VT and 10% MT on the following OBG Side Plates for green tagging;

a)SP574-001-054~065 – deemed acceptable

b)SP340-001-013~024 - deemed acceptable

c)SP536-001-015~028 - deemed acceptable

Please see my TL-6028 on this day for more details.

2)OBG Side Plate SP720-001-054~065 was not done by ZPMC/NDE due to rusty fillet

welds that requires wire brushing.

Summary of Conversations:

No significant conversation ocurred today.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Joshua, Ishibashi, (858) 232-7081, who represents the Office of Structural Materials for your project.

Inspected By:	Lizardo, Joselito	Quality Assurance Inspector
Reviewed By:	Cuellar,Robert	QA Reviewer